

Contact: Carl Davis
200 Jetport Rd.
Brandon, MS 39047
Phone: 601-936-0777



Spey MK 511-8 - S/N 8711

TTSN	9,660.4	TSO	2,355.7
TCSN	6,674	CSO	1,897

PART NAME	PART #	SERIAL #	MOD STD	TOTAL HRS	TOTAL CYC	CYC LIMIT	CYC REMAIN
LP COMP SHAFT	EU35742A	TC170	2982	9,660.4	6,674	20,000	13,326
LP COMP EXT SHAFT	EU62068A	SH789	2983	9,660.4	6,674	20,000	13,326
HP COMP DISC STG 1	JR17214	712CP	2782	9,660.4	6,674	13,000	6,326
HP COMP DISC STG 2	JR18742	364CBZ	5283	7,199.7	4,594	20,000	15,406
HP COMP DISC STG 3	JR18743	632CCA	5283	7,199.7	4,594	20,000	15,406
HP COMP DISC STG 4	JR18744	89CCB	5283	7,199.7	4,594	20,000	15,406
HP COMP DISC STG 5	JR18746	789CBZ	5283	7,199.7	4,594	20,000	15,406
HP COMP DISC STG 6	JR18748	238CBZ	5283	10,599.7	9,263	20,000	10,737
HP COMP DISC STG 7	JR13814	4VW	5283	9,660.4	6,674	20,000	13,326
HP COMP DISC STG 8	JR13815	175TM	5283	9,660.4	6,674	20,000	13,326
HP COMP DISC STG 9	JR13816	613EL	5283	9,660.4	6,674	20,000	13,326
HP COMP DISC STG 10	JR18750	562EAN	5283	7,199.7	4,594	20,000	15,406
HP COMP DISC STG 11	JR18751	472EAM	5283	7,199.7	4,594	20,000	15,406
HP COMP DISC STG 12	JR13820	127EM			6,677	13,000	6,323
HP COMP DISC SEAL STG 12	EU57312	770YG	2651	16,276.7	8,199	13,000	4,801
HP TURB DISC STG 1	AJR30350	709GN	4701	9,660.4	6,674	13,046	6,372
HP TURB DISC STG 2	JYR11312A	768GN	5870	9,660.4	6,674	17,500	10,826
LP TURB DISC STG 1	EU75913A	618BA	3892	UNK	7,631	20,000	12,369
LP TURB DISC STG 2	EU29983	554BG	5155	UNK	3,151	20,000	16,849
LP COMP DRIVE SHAFT	EU46830	838NK	2411	9,660.4	6,674	15,000	8,326
LP TURB SHAFT	EU46832A	485NG	2172	9,660.4	6,674	20,000	13,326
HP TURB SHAFT	JR23586A	34WH	5675	22,031.7	11,891	20,000	8,109
HP COMP REAR SHAFT	EU57333	PABX21632A	2651	2,355.7	1,897	20,000	18,103
HP TURB STG 2 LOC SLEEVE	JR31062	200141D02975	4412	120.85	77	17,500	17,423

ADDITIONAL INFO:

- Last OH – Rolls Royce on 12 Jun 2001
- Last 10 Yr Calendar Inspection - Dallas Airmotive on 01 Jul 2016
- Non-incident
- Performance Run prior to removal completed, results available on request

Disclaimer: Verification of the above provided information shall be the sole responsibility of the buyer/installer. Davis Aviation, Inc. is not responsible and accepts no liability for the use of this information, or for any consequences of any actions taken, or any loss or damage caused, or alleged to have been caused directly, or indirectly on the basis of the information provided above.