

Contact: Carl Davis
200 Jetport Rd.
Brandon, MS 39047
Phone: 601-936-0777



Spey MK 511-8 - S/N 8886

TTSN	10,391.0	TSO	3,626.7
TCSN	9,534	CSO	3,264

PART NAME	PART #	SERIAL #	MOD STD	TOTAL HRS	TOTAL CYC	CYC LIMIT	CYC REMAIN
LP COMP SHAFT	EU35742A	TC692	2982	10,391.0	9,534	20,000	10,466
LP COMP EXT SHAFT	EU62068A	SJ91	2983	10,391.0	9,534	20,000	10,466
HP COMP DISC STG 1	JR17214	949CBD	2782	10,391.0	9,534	13,000	3,466
HP COMP DISC STG 2	JR18742	27CBL	5283	10,391.0	9,534	20,000	10,466
HP COMP DISC STG 3	JR18743	151CCA	5283	12,255.7	14,324	20,000	5,676
HP COMP DISC STG 4	JR18744	121CBV	5283	12,255.7	11,668	20,000	8,332
HP COMP DISC STG 5	JR18746	944CBP	5283	11,750.7	11,853	20,000	8,147
HP COMP DISC STG 6	JR18748	SETP05922	5283	3,626.7	3,257	20,000	16,743
HP COMP DISC STG 7	JR13814	SETP05746	5283	3,626.7	3,257	20,000	16,743
HP COMP DISC STG 8	JR13815	781EAE	5283	10,391.0	9,534	20,000	10,466
HP COMP DISC STG 9	JR13816	84EAH	5283	10,391.0	9,534	20,000	10,466
HP COMP DISC STG 10	JR18750	98EAH	5283	10,391.0	9,534	20,000	10,466
HP COMP DISC STG 11	JR18751	823EAG	5283	10,391.0	9,534	20,000	10,466
HP COMP DISC STG 12	JR13820	249EAG	5283	10,391.0	9,534	13,000	3,466
HP COMP DISC SEAL STG 12	EU57312	648YG	2651	10,391.0	9,534	13,000	3,466
HP TURB DISC STG 1	JR24431	718GAT	5928	3,626.7	3,257	10,000	6,743
HP TURB DISC STG 2	YJR11312A	787GV	4412	10,391.0	9,534	17,500	7,966
LP TURB DISC STG 1	EU75913A	943BH	3892	10,391.0	9,534	20,000	10,466
LP TURB DISC STG 2	EU59228	70BJ	5155	10,391.0	9,534	20,000	10,466
LP COMP DRIVE SHAFT	JR17862	402NT	5097	10,391.0	9,534	20,000	10,466
LP TURB SHAFT	EU60809	707NJ	5155	10,391.0	9,534	20,000	10,466
HP TURB SHAFT	JR23586A	357WP	5675	10,391.0	9,534	20,000	10,466
HP COMP REAR SHAFT	EU57334	864NS	2651	10,391.0	9,534	20,000	10,466
HP TURB STG 2 LOC SLEEVE	NDG4199	8886	4412	10,391.0	9,534	17,500	7,966

ADDITIONAL INFO:

- Last OH – Rolls Royce on 13 Dec 1993
- MOD and Recertification – Rolls Royce on 30 Oct 2006
- Non-incident
- Performance Run prior to removal completed, results available on request

Disclaimer: Verification of the above provided information shall be the sole responsibility of the buyer/installer. Davis Aviation, Inc. is not responsible and accepts no liability for the use of this information, or for any consequences of any actions taken, or any loss or damage caused, or alleged to have been caused directly, or indirectly on the basis of the information provided above.