



Contact: Carl Davis
200 Jetport Rd.
Brandon, MS 39047
Phone: 601-936-0777

ENGINE	SERIAL	TTSN	TCSN	TTSO	TCSO	TTHSI
TPE331-10AV-511B	P102208C	8273.28	6972	4300.68	3139	1768.28
OVERHAUL @	Allied Signal	7/16/1996	3972.6	3833		
	P/N	S/N	TTSN	TTCN		
1st T-Wheel	3108164-2	4-03501-7044	10398.28	12418		
2nd T-Wheel	3102106-9	5-01345-4197	4300.68	3139		
3rd T-Wheel	3102655-2	5-01345-8125	4300.68	3139		
1st Impeller	3107110-2	9-03501-29110	4300.68	3139		
2nd Impeller	893482-4	7-03501-6516	NR	NR		
Seal Plate	3102484-1	950350103029	4300.68	3139		
Comp. Bearing	3101405-1	96-19914-6037	4300.68	3139		

ADDITIONAL INFO:

- No PMA
- Non-incident/Good Logbooks

Disclaimer: Verification of the above provided information shall be the sole responsibility of the buyer/installer. Davis Aviation, Inc. is not responsible and accepts no liability for the use of this information, or for any consequences of any actions taken, or any loss or damage caused, or alleged to have been caused directly, or indirectly on the basis of the information provided above.