



DAVIS

AVIATION, INC

www.davisaviation.com

Contact: Carl Davis
200 Jetport Rd.
Brandon, MS 39047
Phone: 601-936-0777

PT6A-42 PCE-93057

TTSN GG	11,691.8
TCSN GG	10,811
TTSN PS	11,820.1
TCSN PS	10,913
TSO GG	8281.6
CSO GG	8064
TSO PS	8409.9
CSO PS	8166
TSHSI	452.4

PART #	SERIAL #	DESCRIPTION	CSN	CYC LIMIT	CYC REM
3041501	52A474	Rotor Compressor	8064	30,000	21,936
3023112	7H172	Comp Disc 2nd Stage	10,811	20,000	9189
3023113	3F999	Comp Disc 3rd Stage	10,811	20,000	9189
3036793	9A908	Impeller	10,811	20,000	9189
3049291-01	A0011X1D	Comp Turbine Disc	5532	10,000	4468
3029312	A000R6PP	1 st Stage PT Disc	5585	30,000	24,415
3029313	A0011FNY	2nd Stage PT Disc	5585	30,000	24,415

- Last OH by PWV (1/1993) - only one OH since new
- Logs back to Overhaul
- CT & PT's replaced with new during repair at GG TSO:2289.4 (3/2002)
- Exhaust Duct Repair by Standard Aero (6/2015)

Disclaimer: Verification of the above provided information shall be the sole responsibility of the buyer/installer. Davis Aviation, Inc. is not responsible and accepts no liability for the use of this information, or for any consequences of any actions taken, or any loss or damage caused, or alleged to have been caused directly, or indirectly on the basis of the information provided above.