



Contact: Carl Davis
200 Jetport Rd.
Brandon, MS 39047
Phone: 601-936-0777

PT6A-112
PCE-PA0022

TTSN	4162.4
TCSN	1546
TSO	N/A
CSO	N/A
TSHSI	2353.8

PART #	DESCRIPTION	CSN	CYC LIMIT	CYC REM
3013111	Compressor Hub	1546	19,000	17,454
3013712	Compressor Disc 2nd Stage	1546	24,000	22,454
3011713	Compressor Disc 3rd Stage	1546	25,000	23,454
3013176	Impeller	1546	19,000	17,454
3013411	Compressor Turbine Disc	1546	16,000	14,454
3031012	1 st Stage PT Disc	1546	20,000	17,454

- EASA Form-1 Inspection on 07-Mar-2019
- Non-incident
- Full Logbooks since new
- Last HSI by SECA on 23-Mar-2011

Disclaimer: Verification of the above provided information shall be the sole responsibility of the buyer/installer. Davis Aviation, Inc. is not responsible and accepts no liability for the use of this information, or for any consequences of any actions taken, or any loss or damage caused, or alleged to have been caused directly, or indirectly on the basis of the information provided above.