



Contact: Carl Davis
 200 Jetport Rd.
 Brandon, MS 39047
 Phone: 601-936-0777

PT6A-28 PCE-PG0282

| | |
|--------------|----------|
| TTSN | 10,485.4 |
| TCSN | 10,936 |
| TSO | 4791.0 |
| CSO | 4382 |
| TSHSI | 1752.4 |

| PART # | SERIAL # | DESCRIPTION | CSN | CYC LIMIT | CYC REM |
|---------------|-----------------|-------------------------------|------------|----------------------|--------------------|
| 3013111 | RWA15A062 | Rotor Compressor | 10,936 | 19,000 | 8064 |
| 3013712 | A001R0MB | Comp Disc 2nd Stage | 10,936 | 24,000 | 13,064 |
| 3011713 | A001P8XR | Comp Disc 3rd Stage | 10,936 | 25,000 | 14,064 |
| 3013176 | EAAA000L478 | Impeller | 10,936 | 19,000 | 8064 |
| 3013411 | A0013LWA | Comp Turbine Disc | 13,274 | 16,000 | 2726 |
| 3022412 | A001RB2X | 1 st Stage PT Disc | 10,936 | 20,000 | 9,064 |

ADDITIOINAL INFO:

- Last OH by Standard Aero (9/2012)
- Logs back to birth
- Last HSI by Standard Aero (9/2016) - CT Blades Overhauled

Disclaimer: Verification of the above provided information shall be the sole responsibility of the buyer/installer. Davis Aviation, Inc. is not responsible and accepts no liability for the use of this information, or for any consequences of any actions taken, or any loss or damage caused, or alleged to have been caused directly, or indirectly on the basis of the information provided above.