



DAVIS

AVIATION, INC.

www.davisaviation.com

Contact: Carl Davis
200 Jetport Rd.
Brandon, MS 39047
Phone: 601-936-0777

PT6A-41

PWV-79199

TTSN	14,889.3
TCSN	13,514
TSO	1462.5
CSO	1531
TSHSI	N/A

PART #	DESCRIPTION	CSN	CYC LIMIT	CYC REM
3023611	Hub Assembly	7,016	20,000	12,984
3023112	Compressor Disc 2nd Stage	10,082	20,000	9,918
3023113	Compressor Disc 3rd Stage	15,741	20,000	4,259
3017463	Impeller	13,514	20,000	6,486
3049291-01	Compressor Turbine Disc	1,331	10,000	8,669
3029312	1 st Stage PT Disc	7,009	30,000	22,991
3029313	2 nd Stage PT Disc	7,009	30,000	22,991

ADDITIONAL INFO:

- Last OVH by PWV January 2001
- New CT Blades at Overhaul

Disclaimer: Verification of the above provided information shall be the sole responsibility of the buyer/installer. Davis Aviation, Inc. is not responsible and accepts no liability for the use of this information, or for any consequences of any actions taken, or any loss or damage caused, or alleged to have been caused directly, or indirectly on the basis of the information provided above.