



DAVIS
AVIATION, INC

www.davisaviation.com

Contact: Carl Davis
200 Jetport Rd.
Brandon, MS 39047
Phone: 601-936-0777

PT6A-42
PCE-RC0006

TTSN	11,984.4
TCSN	11,191
TSO	3546.7
CSO	3773
TSHSI	1662.5

PART #	SERIAL #	DESCRIPTION	CSN	CYC LIMIT	CYC REM
3041501	43B800	Rotor Compressor	11,191	30,000	18,809
3023112	51B094	Comp Disc 2nd Stage	11,191	20,000	8,809
3023113	51B109	Comp Disc 3rd Stage	11,191	20,000	8,809
3036793	8F415	Impeller	11,191	20,000	8,809
3049291-01	A000DMHH	Comp Turbine Disc	8155	10,000	1845
3029312	6F452	1 st Stage PT Disc	25,382	30,000	4618
3029313	6R521	2nd Stage PT Disc	13,905	30,000	16,095

- Last OH by Standard Aero (12/2006)
- Logs back to birth
- Last HSI by Standard Aero (2/2011)
- Repaired by Standard Aero - rental engine eval (1/2013)

Disclaimer: Verification of the above provided information shall be the sole responsibility of the buyer/installer. Davis Aviation, Inc. is not responsible and accepts no liability for the use of this information, or for any consequences of any actions taken, or any loss or damage caused, or alleged to have been caused directly, or indirectly on the basis of the information provided above.