



DAVIS
AVIATION, INC.

Giving Wings to Truth
www.davisaviation.com

Contact: Carl Davis
200 Jetport Rd.
Brandon, MS 39047
Phone: 601-936-0777

PW617F-E
PCE-LC0267

TTSN	3,476.9
TCSN	2,996
TSO	3,476.9
CSO	2,996

PART #		DESCRIPTION	CYC LIMIT	CYC REM
35C3881-01	AATPWACR005	Fan Rotor	10,500	7,504
35C4716-01	AAPPIAPC2062	Impeller and Shaft	10,500	7,504
35C4781-01	AATPWAC0115	HP Compressor Rotor	10,500	7,504
35C3091-01	CRAZAEGA036	HP Turbine Disk	5,250	4,431
35C4620-01	KWA4947302	LP Compressor Shaft	10,500	7,504
35C5392-01	CRAZADLZ110	LP Turbine Disk	10,500	7,504

ADDITIONAL INFO:

- Good Logbooks

Disclaimer: Verification of the above provided information shall be the sole responsibility of the buyer/installer. Davis Aviation, Inc. is not responsible and accepts no liability for the use of this information, or for any consequences of any actions taken, or any loss or damage caused, or alleged to have been caused directly, or indirectly on the basis of the information provided above.